UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,938,122 B2

Page 1 of 1

DATED

: August 30, 2005

INVENTOR(S) : David Meiri et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Line 27, reads, "FP 40b, FP 40c, FP 40c, FP 40d," and should read -- FP 40b, FP 40c, FP 40d, --.

Lines 57-58, reads "system data storage system" and should read -- data storage system --.

Column 6,

Line 18, reads "port 34d to 34g," and should read -- port 34d to port 34g, --.

Column 7,

Line 48, reads "port is has failed" and should read -- port has failed --. Line 66, reads "to a an 'oxff" and should read -- to a 'oxff' --.

Column 10,

Line 12, reads "an associated pointed" and should read -- an associated pointer --.

Signed and Sealed this

Twenty-first Day of March, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office